09-50026-mg Doc 11578-2 Filed 04/05/12 Entered 04/05/12 15:13:46 Exhibit Ex. B -- Nationwide Claims Summary Pg 1 of 2

EXHIBIT B

NMIC	GM claims - July, 2009								
						Type of claim			
Clm#	Insured's name	YR	Make	Model	Claim amount inc ded	fire	O&C (ves or no)	Cause- defective nart - specify)	Add'l info
9112C443873 1/16/09	Ē	4	Saturn	Vue	\$642.96	FTC fire	L	heater element shorted and burned through cover- seat	l
9247K302435 1/17/08	9247K302435 1/17/08 [redacted for privacy]	0	Buick	Regal	\$6,294.75	FTC fire	c	engine fire	
9234K535053 01/14/09	9234K535053 01/14/09 [redacted for privacy]	80	Gmc	Yukon	\$36,924.00	FTC fire	y	fit seat master switch for power recliner was the origin of fire	
9247H498382 2/5/09	[redacted for privacy]	-	Buick	Regal	\$1,056.49	FTC fire	u	engine fire-manifold fire	
5219A902884 9/30/08	[redacted for privacy]	4	Chevy	Colorado	\$10,373.53	FTC fire	χ	fuel fire	W/TD
6631P512913 10/29/08	6631P512913 10/29/08 [redacted for privacy]	9	Chevy	Trailblazer	\$14,769.65	FTC fire	^	a resitance heating connection in the d/s door	
66310624439 7/03/98	[redacted for privacy]	98	Caddy	Seville	\$42,154.87	FTC fire	٨	short within the alternator	w/Sub Attny
5345Q588113 7/3/08	[redacted for privacy]	0	Chevy	Blazer	\$4,337.14	Coll clm	u	IV came out of gear, while parked and no keys in iv at tol	
5345V436338 2/21/09	[redacted for privacy]	7	Chevy	Aveo	\$10,561.29	Ftc Fire	\	fuel leak in the engine compartment near the main fuel injection system.	
6631P878575 3/2/09	[redacted for privacy]	7	GMC	Yukon	\$39,427.31	Ftc Fire	Y	electrical failure in engine compartment	
7709 20 009190 6/6/09	7709 20 009190 6/6/09 [redacted for privacy]	4	Chevy	Suburban	\$16,406.54	Ftc Fire	\	origin rear speaker	Additional sums were paid on this claim, to bring the total paid to \$16556.34.
5345Q246302 6/15/08	5345Q246302 6/15/08 [redacted for privacy]	80	Chevy	Colorado	\$24,676.94	Ftc Fire	>	driver side seat heating / wires fuse cause	
9234N018339 6/12/09	[redacted for privacy]	သ	GMC	Envoy	\$15,907.32	Ftc Fire	>	originated in area to the right of steering column	
9121-20-037214 8/14/08	9121-20-037214 8/14/08 [redacted for privacy]	ည	Chevy	Avalanche	\$22,269.22	Ftc Fire	>	in dash electrical behind AC and heating controls	
6132N595756 6/22/08	[redacted for privacy]	ø	Chevy	Silverado	\$23,357.08	Ftc Fire	>	OEM cig lighter circuit	
6139M061097 1/2/09	6139M061097 1/2/09 [redacted for privacy]	7	Pont	99	\$11,311.00	Ftc fire	>	passengers side air bags	
9234N070280 06/07/09	9234N070280 06/07/09 [redacted for privacy]	က	SplO	Alero	\$5,980.50	Ftc Fire	>	failure of the gas line in the engine compartment	ho xfile 92-610995
9121-20-046209 3/12/09	9121-20-046209 3/12/09 [redacted for privacy]	9	Saab	9-7x	\$18,939.02	Ftc Fire	>	Engine Fire	GM ext warr
9247K127052 3/3/09	[redacted for privacy]	4	Chevy	Silverado	11949.05	Ftc Fire	λ	dash fire	
5345 Q 754296 7/7/09	[redacted for privacy]	7	Chevy	Silverado	23129.32	Ftc Fire	>	d/s engine compartment	
7246 20 022711 5/19/09	7246 20 022711 5/19/09 [redacted for privacy]	80	GMC	Sierra	40861.04	Ftc Fire	>	origin undetermined, attempting to verify w/ho carrier	home dmg insured w/Sterling Ins
5437A854779 6/19/09	[redacted for privacy]	00	GMC	Hummer	25230.5	Ftc Fire	>	electrical malfuction under the dash	
5837 D 279962 1/14/08	5837 D 279962 1/14/08 [redacted for privacy]	7	Saturn	lon	12911.52	Ftc Fire	>	rear upper section of engine compartment	file w/td in PA
					\$419,471.04				
		l							